



Crack Monitoring Record

Indicate on the diagrams below the Crack Monitor movement at each reading after the crack widths have been measured using the Crack Width Gauge.


For each reading:

- Measure current crack width with Crack Width Gauge.
- If monitors are equipped with post fixtures (spigots), measure total distance between them with Digital Calipers.
- Record cursor position of Crack Monitor on the diagrams below to track ongoing movement of the crack. Plus (+) represents crack opening and minus (-) represents crack closing on the horizontal scale.

Project: _____

Location of Monitor: _____


Date of Reading: _____



Distance Between Spigots: _____ mm

Crack Width: _____ mm


Date of Reading: _____



Distance Between Spigots: _____ mm

Crack Width: _____ mm


Date of Reading: _____



Distance Between Spigots: _____ mm

Crack Width: _____ mm


Date of Reading: _____



Distance Between Spigots: _____ mm

Crack Width: _____ mm


Date of Reading: _____



Distance Between Spigots: _____ mm

Crack Width: _____ mm

Date of Reading: _____



Distance Between Spigots: _____ mm

Crack Width: _____ mm